# Highlights of the Coal Mine Safety and Health Rules and Regulations

Matuwid S. Lagang
Senior SRS, Coal and Nuclear Minerals Division
Energy Resource Development Bureau

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

# **Legal Basis**

### 1. Republic Act (RA) No. 7638:

"The Department of Energy (DOE) Act of 1992"

-An Act Creating the Department of Energy Rationalizing the Organization and Functions of Government Agencies Related To Energy and for Other Purposes

### 2. Presidential Decree No. 972 "The Coal Development Act of 1976"

-declared as a policy of the state to immediately accelerate the exploration, development, exploitation, production, and utilization of the country's coal resources

# Legal Basis

### 3. BED Circular No. 1 series of 1978

"Coal Mine Safety Rules and Regulations"

- governs the mandatory health and safety standards and safety of laborers and employees in coal mining operations in the Philippines

### 4. Philippine's Ratification of ILO C176

"Safety and Health in Mines Convention, 1995 (No. 176)"

- considers that the workers have a need for, and a right to, information, training and genuine consultation on and participation in the preparation and implementation of safety and health measures concerning the hazards and risks they face in the mining industry

### 5. Bureau of Energy Circular No. 81-11-10

"Guidelines for Coal Operations in the Philippines"

- sets the guidelines for applying for Coal Operating Contract including penalties for non-compliance of the requirements stated in the Circular

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

- 2010 and 2014 Initiatives to review 1978 BED CMSRR (comments and suggestions were gathered and evaluated)
- 26 July 2017, Manila Consultation Workshop on the Harmonization of 1978
  BED CMSRR with International Labour Organization Convention on Safety and
  Health in Mines, 1995 (ILO C176). Resulted to the preparation of the initial draft of
  the 2018 CMSHRR. Took into account the inputs from this activity and the inputs
  from previous reviews.
- **Series of Consultative Process** to provide a better understanding and appreciation of BED 1978 CMSRR in harmonization with ILO C176 directly to the representatives of employers and workers. Comments/inputs were also gathered and evaluated for their relevance to the revision process.

| No. | Date        | Venue  |
|-----|-------------|--|
| 1   | 26 Jul 2017 | DOE Audio Visual Room, DOE Taguig City                                       |
| 2   | 16 Oct 2017 | Semirara Mining and Power Corp.<br>minesite, Semirara Is., Caluya, Antique   |
| 3   | 24 Oct 2017 | PNOC Base Camp, Malangas, Zamboanga,<br>Sibugay                              |
| 4   | 17 Nov 2017 | Kamias Function Room, Casablanca Suite,<br>Benny Imperial St., Legazpi City  |
| 5   | 23 Nov 2017 | Summit C Function Room, Summit<br>Galleria Hotel, Gen Maxilom St., Cebu City |



Participants DOE Audio Visual Room, DOE, Bonifacio Global City, Taguig 26 July 2017



SMPC, Semirara Is., Caluya, Antique 16 October 2017



Base Camp, PNOC-EC, Malangas, Zamboanga, Sibugay Province 24 October 2017



Kamias Room, Casablanca Suites, Benny Imperial St. (Alternate Road), Legazpi City, Albay 17 November 2017





**Participants** 

Consultation Workshop on the Harmonization of BED Circular No.1 with ILO C176 Summit Galleria Hotel, Gen. Maxilom Ave. Ext., B. Benedicto St., Cebu City, Cebu 23 November 2017

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

### **ILO C176**

- International Labour Organization Convention on Safety and Health in Mines, 1995 (C176)
- Adopted at the 82<sup>nd</sup> International Labour Conference of the ILO held in Geneva
- Date of adoption 22 Jun 1995
- Date of enforcement 05 Jun 1998
- Classification Industries and Occupation
- Subject Occupational Safety and Health

### **ILO C176**

- Philippines Ratification
  - Senate Resolution No. 115 (Resolution Concurring in the Ratification of the Safety and Health in Mines Convention, 1995)
  - Resolution adopted on 08 Dec 1997
  - During the 3<sup>rd</sup> Regular Session of the 10<sup>th</sup> Congress
  - Ernesto M. Maceda (Senate President)
  - Ratified on 27 Feb 1998

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

# **Scope of Coverage**

This Circular shall apply to all Operators and Workers involved in coal mining operations in the Philippines

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

# **Objectives**

- 1. The main purpose of the revision is to make the coal mine safety rules and regulations more applicable to the present local coal mining conditions and adopts the provisions of ILO C176
- 2. Takes into account the Energy Resiliency Plan of the Department

### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

## 2018 CMSHRR Harmonized with ILO C176

07 2018 CMSHRR Harmonized with ILO C176.pdf

| 1978 CMSRR   | 2018 CMSRR  | Remarks   |
|--|---|---|
| Chapter I "General Provisions"   |   |   |
| 1.   | NEW "Safety and Health Policy Statement" is indicated in page 2.  | In compliance with ILO C176.  |
| 2. REVISED Rule 1 under Section 1 "Accidents"  | NOW Rule 1 under the same Section 1 "Accidents"   | Notification of occurrence of accident shall be within 24 hours. Failure to notify, fine of |
| "The operator of a coal mine shall, using the fastest available means of communication, notify the Bureau of the occurrence of the following accidents:" | "The Resident Manager of a coal mine shall notify the Bureau within twenty-four (24) hours using the fastest available means of communication the occurrence of the following accidents:" | <b>P20,000.00</b> (per Rule 922).   |

|    | 1978 CMSRR   | 2018 CMSRR  | Remarks   |
|----|--|---|---|
|    | Chapter I "General Provisions"   |   |   |
| 3. | <b>DELETED</b> Rule 2 under Section 1 "Accidents"  | NOW Rule 2 under the same Section 1 "Accidents"   | Failure to report within 5 working days after the accident, fine of |
|    | "When any personal injury results in the death of the person injured, the manager must give notice to the Bureau without delay." | "A formal report of the accident referred to in Rule 1 shall be forwarded to the Bureau within five (5) working days after the accident." | <b>P20,000.00</b> (per Rule 922).                                   |
| 4. | <b>REVISED</b> and <b>MODIFIED</b> Rule 8<br>Responsibilities of the<br>Operator.  | NOW Rule 8 includes responsibilities of the Employer or Operator as required by ILO C176.   | In compliance with ILO C176.  |

|    | 1978 CMSRR   | 2018 CMSRR   | Remarks  |
|----|--|--|--|
|    | Chapter I "General Provisions"   |  |  |
| 5. | <b>DELETED</b> Rule 11 and Rule 12,<br>Responsibilities of Shift Bosses and<br>Capatazes, and Fireboss,<br>respectively. | <b>NOW</b> Rule 11 Responsibilities of Shift Supervisor.                               | Responsibilities of the Shift Bosses and Capatazes, as well as Fireboss are assumed by the Shift Supervisor. |
| 6. | <b>REVISED</b> and <b>MODIFIED</b> Rule 13 Responsibilities of the Employee.   | NOW Rule 12 includes responsibilities of the Worker as required by ILO C176.           | In compliance with ILO C176.   |
| 7. |  | <b>NEW</b> Rule 13 lists the responsibilities of the Safety and Health Representative. | In compliance with ILO C176.   |

| 1978 CMSRR  | 2018 CMSRR                                   | Remarks   |
|---|--|---|
| Chapter I "General Provisions"  |  |   |
| 8. <b>DELETED</b> entire Section 3  | <b>NEW</b> Section 3 "Organization of Safety | The revised CMSHRR requires                                     |
| "Classification of Mines"   | Department"                                  | all coal mines to have a safety<br>Department regardless of the |
| Mines were classified into "Class A" with 100 or more employees at any one time, and "Class B" with less than 100 employees at any one time | No more classification of mines              | number of employees.  |

|    | 1978 CMSRR  | 2018 CMSRR   | Remarks   |
|----|---|--|---|
|    | Chapter I "General Provisions"  |  |   |
| 9. | REVISED Rule 18 "Qualification of a Safety Engineer (Appendix B)" under Section 4 "Qualification of a Safety Engineer and Safety Inspector" | NOW Rule 16 with the same heading and under the same Section 4  a. For permanent registration i. Must be duly registered and currently licensed mining engineer. ii. With at least two (2) years working experience in U/G mining operations for U/G coal mines or surface mining operations for surface coal mines. iii. Must have completed forty (40) hours of Basic Occupational Safety and Health Training inclusive of confined space training module. | New requirements for registration of Permanent or Temporary Safety Engineer Permit. |

| 19                            | 978 CMSRR   | <b>2018 CMSRR</b>  | Remarks   |  |
|-------------------------------|---|--|---|--|
| Chapter                       | Chapter I "General Provisions"  |  |   |  |
| Safety Engine<br>Section 4 "Q | e 18 "Qualification of a eer (Appendix B)" under ualification of a Safety d Safety Inspector" | <ul> <li>b. For temporary registration: <ol> <li>Duly registered and currently licensed mining engineer but does not possess the requirements in Rule 16 (a) ii and iii.</li> <li>Any other duly registered and currently licensed engineer, geologist, metallurgist, chemist, with at least one (1) year experience as safety inspector in U/G or surface coal mine.</li> </ol> </li> </ul> | New requirements for registration of Permanent or Temporary Safety Engineer Permit. |  |

| 1978 CMSRR  | 2018 CMSRR   | Remarks  |
|---|--|--|
| Chapter I "General Provisions"  |  |  |
| 10. REVISED Rule 19 "Who may be registered as Safety Inspector" under Section 4 "Qualification of a Safety Engineer and Safety Inspector" | NOW Rule 17 with the same heading and under the same Section  e. Any high school undergraduate with at least ten (10) years experiences in safety work in mining operation | Added item e in the 2018 CMSHRR.   |
| 11.   | <b>NEW</b> Section 5 "Application for<br>Permanent or Temporary Safety<br>Engineer's / Safety Inspector Permit"  | Payment of registration is now P550.00 (Based on DOE CY 2013 Schedule of Fees and Charges) |

| 1978 CMSRR   | 2018 CMSRR   | Remarks   |
|--|--|---|
| Chapter I "General Provisions"                       |  |   |
| 12.  | New Rule 21 "The Operator shall establish an adequate training and retraining programs and comprehensible instructions for workers, at no cost to them, on safety and health matters as well as on the work assigned." | Operator of coal mine needs<br>to establish and implement a<br>procedure on Training<br>Program |
| Chapter II "Underground Mining Ru                    | les"   |   |
| <b>13. REVISED</b> Rule 24 under Section 1 "General" | NOW Rule 23 under Section 1 "General Provisions"   | Specific dimensions for vertical shaft and tunnel   |
| Dimensions of exit to the surface were not specified | Vertical shaft dimension shall be at least 6 x 4 feet and for tunnel dimension shall be at least 5 x 7 feet  |   |

| 1978 CMSRR   | 2018 CMSRR   | Remarks  |
|--|--|--|
| Chapter II "Underground Minin  |  |  |
| <b>14. REVISED</b> Rule 32 under Section 1 "General"   | <b>NOW</b> Rule 32 under the same Section 1 "General"  | Sleeping underground is prohibited. No more exception. |
| Management option to allow employee to sleep underground   | "No worker shall be allowed to sleep underground."   |  |
| <b>15. REVISED</b> Rule 39 under Section 2 "Escapeways"  | <b>NOW</b> Rule 38 under the same Section 2 "Escapeways"   | Exception is deleted                                   |
| "Except in situations where the height of the coalbed is less than 150 centimeters, escapeways should be maintained at a height of at least 150 centimeters (excluding necessary roof support) and the travelway in such escapeway should be maintained at a width of at least 200 centimeters." | "Regardless of the height of the coal bed, the escapeway shall be maintained at the height of at least 150 centimeters (excluding necessary roof support) and the travelway in such escapeway shall be maintained at the width of at least 200 centimeters." |  |

| 1978 CMSRR  | 2018 CMSRR   | Remarks   |  |  |
|---|--|---|--|--|
| Chapter II "Underground Mining  | Chapter II "Underground Mining Rules"  |   |  |  |
| <b>16. MODIFIED</b> Rule 43 under Section 2 "Escapeways"  | <b>NOW</b> Rule 42 under the same Section 2 "Escapeways"   | Shorter interval for escapeways inspection                                  |  |  |
| "All escapeways shall be examined in their entirety at least once a month by a certified person." | "All escapeways shall be examined in their entirety every fifteen (15) days by the safety engineer and a record of such inspection shall be maintained." |   |  |  |
| 17. REVISED Rule 46 under Section 2 "Escapeways"  | NOW Rule 45 under the same Section 2 "Escapeways"  | Drills need to be properly documented as evidence of compliance to Rule 45. |  |  |
| No specified schedule for practice escapeway drills   | Practice escapeway drills shall be conducted at least twice a year.  |   |  |  |

| 1978 CMSRR  | 2018 CMSRR   | Remarks  |  |  |
|---|--|--|--|--|
| Chapter II "Underground Mining  | Chapter II "Underground Mining Rules"                    |  |  |  |
| <b>18. REVISED</b> Rule 49 (a) under Section 3 "Mine Maps"                                  | <b>NOW</b> Rule 48 under the same Section 3 "Mine Maps"  | Intervals, now become every 3 months                               |  |  |
| "Mine maps shall be revised and supplemented at intervals of not more than six (6) months." | "Mine maps shall be updated and supplemented quarterly." |  |  |  |
| 19. REVISED Rule 50 Section 3 "Mine Maps"   | NOW Rule 49 under the same Section 3 "Mine Maps"         | Failure to submit quarterly a copy of the mine maps within fifteen |  |  |
| "The coal mine map and any revision and   |  | (15) days following the end of                                     |  |  |
| supplement thereof shall be available for   | "The mine maps including revision and                    | each quarter, fine of (per Rule                                    |  |  |
| inspection by the Bureau or its   | supplement thereof shall be available for                | 922):  |  |  |
| authorized representative. The Operator   | inspection by the Bureau or its authorized               |  |  |  |
| shall furnish the Bureau or its authorized  | representative. The Operator shall submit                | 1 <sup>st</sup> offense – <b>P20,000.00</b>                        |  |  |
| representative upon request, one or   | to the Bureau a copy of the mine maps                    | 2 <sup>nd</sup> offense – <b>P50,000.00</b>                        |  |  |
| more copies of such maps and any  | quarterly within fifteen (15) days after the             | 3 <sup>rd</sup> offense – <b>Cancellation of</b>                   |  |  |
| revision and supplement thereof."   | end of each quarter."                                    | contract   |  |  |

| 1978 CMSRR  | 2018 CMSRR   | Remarks |
|---|--|---------|
| Chapter II "Underground Mining Rules"   |  |         |
| <b>20. MODIFIED</b> Rule 61 under "A. Main Fans" of Section 4 "Ventilation"   | <b>NOW</b> Rule 60 under the same "A. Main Fans" of Section 4 "Ventilation"  |         |
| <b>DELETED</b> "The minimum quantity of air in any coal mine reaching each working face shall be 30 cubic meters a minute."   | REPLACED BY " and the volume and velocity of the current of air shall be at least 1.0m/sec of air sufficient to dilute, render harmless, and to carry away, flammable, explosive, noxious, and harmful gases, dust, and smoke and explosive fumes."                                |         |
| 21. MODIFIED Rule 69 under "C. Auxiliary Fan" of Section 4 "Ventilation" "In places where auxiliary fans are used, in a manner to prevent accumulation of methane." | NOW Rule 68 under the same "C. Auxiliary Fan" of Section 4 "Ventilation"  ADDED "In places where auxiliary fans are used, in a manner to prevent accumulation of methane. Prior to resumption of work in such places, auxiliary fans shall first be reactivated 15 to 20 minutes." |         |

| 1978 CMSRR  | 2018 CMSRR  | Remarks |
|---|---|---------|
| Chapter II "Underground Mining Rules"   |   |         |
| <b>22. MODIFIED</b> Rule 75 under "D. Bleeders, Doors, Overcasts and Undercasts" of Section 4 "Ventilation"   | NOW Rule 74 under the same "D. Bleeders, Doors, Overcasts and Undercasts" of Section 4 "Ventilation"  |         |
| "The methane content of the air current in the bleeder split at the point where such split enters any other air split should not exceed 2.0 volume per centum." | "The methane content of the air current in the bleeder split at the point where such split enters any other air split shall not exceed <b>1.0</b> volume per centum." |         |

| 1978 CMSRR                                       | 2018 CMSRR                              | Remarks  |
|--|---|--|
| Chapter II "Underground Mining Rules"            |   |  |
| 23. MODIFIED Rule 76 under "D.                   | NOW Rule 75 under the same "D.          |  |
| Bleeders, Doors, Overcasts and                   | Bleeders, Doors, Overcasts and          |  |
| Undercasts" of Section 4 "Ventilation"           | Undercasts" of Section 4                |  |
|  | "and the concentration of methane       |  |
| " and the concentration of                       | should not exceed <b>1.0 volume per</b> |  |
| methane should not exceed 2.0 volume per centum" | centum"                                 |  |
| <b>24. REWORDED</b> Rule 81 under "E. Mine       | NOW Rule 80 under the same "E.          | Re-arrange wording of Rule 81  |
| Gases" under Section 4                           | Mine Gases" of Section 4                | of the previous CMSRR  |
| "Ventilation"                                    |   |  |
| <b>25. REVISED</b> Rules 82 – 431                | <b>NOW</b> Rules 81 – 408               | "Qualified person" in previous rules is replaced by "Safety Engineer." |

| 1978 CMSRR                                | 2018 CMSRR   | Remarks  |
|---|--|----------|
| Chapter II "Underground Mining Rules"     |  |          |
| 26. Section 15 "Mine Rescue Organization" | ADDED Rule 410 in the same Section 15 "Mine Rescue Organization"  "Underground coal mines employing less than one hundred (100) workers underground at any one time shall cluster with other underground mines located within the same region and shall establish a common mine rescue team. A Memorandum of Agreement shall be established among the underground coal mines in order to operationalize the mine rescue team." | New rule |

| 1978 CMSRR   | 2018 CMSRR  | Remarks   |
|--|---|---|
| Chapter III "Rules on Surface Operations"                        |   |   |
| <b>27. DELETED</b> entire Section 4 "Aerial Tramways"            | <b>NEW</b> Section 4 "Truck Haulage"<br>Rules 520 – 539                             | Inputs from TWG for surface operation                       |
| 28.  | <b>NEW</b> Section 5 "Operation of Bulldozers, Graders and Loaders" Rules 540 – 547 | Inputs from TWG for surface operation                       |
| 29. RENUMBERED Section 5 "Coal and Refuse Piles" Rules 530 – 544 | NOW Section 6 "Coal and Refuse<br>Piles"<br>Rules 548 – 561                         | Retain same provisions (rules) except for the numbering     |
| 30.  | <b>NEW</b> Section 7 "Bucket Wheel<br>Excavator (BWE)"<br>Rules 562 – 587           | As a result of the mining experience of Semirara Coal Corp. |

| 1978 CMSRR             | 2018 CMSRR   | Remarks   |
|------------------------|--|---|
| Chapter V "Explosives" |  |   |
| 31.                    | NEW Rule 638 under Section 1 "General Provisions"  "A quarterly Inventory of Explosive and Blasting Accessories Report shall be submitted to the Bureau within the first ten (10) days following the end of each quarter." | Failure to submit quarterly within the first ten (10) days following the end of each quarter, fine of (per Rule 922):  1st offense – P20,000.00  2nd offense – P40,000.00  3rd offense – P50,000.00  4th offense – Cancellation of contract |

| 1978 CMSRR             | 2018 CMSRR  | Remarks   |
|------------------------|---|---|
| Chapter V "Explosives" |   |   |
| 32.                    | NEW Rule 639 under Section 1 "General Provisions"  "In case where a sub-contractor performs the handling, transport, storage and use of explosive, the Operator shall seek the approval of the Bureau of the sub-contract agreement in accordance with applicable Department circulars on sub-contracting." | Per BED Circular No. 82-09-09 issued on Sept 1982 and BED Circular No. 82-09-09A issued on Dec 1982 |
| 33.                    | NEW Rule 640 under Section 1 "General Provisions"   |   |
|                        | "The Operator shall be responsible and accountable for the safety and performance of the sub-contractor, as well as compliance to this Circular."   |   |

| 1978 CMSRR                         | 2018 CMSRR   | Remarks                      |
|------------------------------------|--|------------------------------|
| Chapter VI "Health and Sanitation" |  |                              |
| 34.                                | <b>NEW</b> Rule 761 under Section 1 "General Provisions"   | In compliance with ILO C176. |
|                                    | 'The coal Operator shall ensure the provision of regular health surveillance of workers exposed to occupational health hazards in the mining operation." |                              |

| 1978 CMSRR  | 2018 CMSRR   | Remarks         |
|---|--|-----------------|
| Chapter VII "Electricity"   |  |                 |
| 35.   | "All electrical installations, constructions and equipment shall be in accordance with the provisions of the latest edition of the Philippine Electrical Engineering Code.  Operations, maintenance and repair works of electrical equipment or machinery shall be done by qualified and duly authorized workers." | Added provision |
| <b>36. MODIFIED</b> Rule 794 under Section 1 "General Provisions"   | NOW Rule 779 under same<br>Section 1 "General Provisions"  |                 |
| "All power circuits and electric equipment shall be de-energized when necessary for trouble shooting or testing." | "All power circuits and electric equipment shall be de-energized when necessary for trouble shooting or testing. Appropriate lock-out and tag-out procedures shall be implemented."  |                 |

| 1978 CMSRR   | 2018 CMSRR  | Remarks   |
|--|---|---|
| Chapter VII "Electricity"                                      |   |   |
| 37. DELETED Section 4 "Trolley Wires and Trolley Feeder Wires" |   | Use of trolley and trolley feeder wires are not adoptable to Philippine underground coal mines, which are mostly gassy. |
| Chapter VIII "Mechanical Safety Rules"                         |   |   |
| 38.  | "Mechanical work" means the construction, inspection, testing, calibrating, maintenance, or alteration of mechanical equipment in accordance with the latest edition of the Philippine Society of Mechanical Engineering Code." | Added provision   |

| 1978 CMSRR  | 2018 CMSRR  | Remarks   |
|---|---|---|
| Chapter IX "Exploration"                            |   |   |
| 39.   | NEW Chapter X "Exploration" with 4 sections   | The 2018 CMSHRR now includes safety practices in exploration activities |
|   |   | Inputs from TWG for exploration   |
| Chapter X "Miscellaneous Safety Rules"              |   |   |
| <b>40. TRANSFERRED</b> Section 3 "Diamond Drilling" | TRANSFERRED to Section 2 "Drilling" under Chapter III "Rules on Surface Operations" |   |
| 41.   | <b>NEW</b> Section 4 "Storage and Use of Chemicals and Hazardous Materials"         | Rules on safe handling of chemicals and hazardous substances            |

| 1978 CMSRR                     | 2018 CMSRR  | Remarks |
|--------------------------------|---|---------|
| Chapter XI "Powers and Duties" |   |         |
| 42.                            | NEW Rule 918  |         |
|                                | "The Director of the Energy Resource Development Bureau shall have the power and authority to suspend any particular activity or operation when such activity or operation causes or will cause imminent danger, or recommend the suspension of the Coal Operating Contract until necessary actions are taken." |         |

| 1978 CMSRR                     | 2018 CMSRR   | Remarks |
|--------------------------------|--|---------|
| Chapter XII "Penal Provisions" |  |         |
| 43.                            | NEW Rule 922   |         |
|                                | "Pursuant to Chapter XI of this Circular, the Director shall impose administrative fines and penalties for the following violations:   |         |
|                                | a. Failure to notify the Bureau within twenty-four (24) hours using the fastest available means of communication the occurrence of any accident set forth in Rule 1, Section 1, Chapter I of this Circular: Fine of P20,000.00 |         |
|                                | b. Failure to submit to the Bureau the formal report of the accident set forth in Rule 1, Section 1, Chapter I of this Circular within five (5) working days after the accident: Fine of P20,000.00                            |         |

| 1978 CMSRR                     | 2018 CMSRR   | Remarks |
|--------------------------------|--|---------|
| Chapter XII "Penal Provisions" | •  |         |
| 43.                            | c. Failure or late submission of monthly accident report and minutes of monthly safety meeting within the first ten (10) days of the succeeding month:                           |         |
|                                | 1 <sup>st</sup> offense – <b>P20,000.00</b> 2 <sup>nd</sup> offense – <b>P50,000.00</b> with  warning of cancellation  3 <sup>rd</sup> offense – <b>Cancellation</b> of contract |         |
|                                | d. Failure to register or renew permit for permanent or temporary safety engineer or safety inspector:   |         |
|                                | i. Within one (1) month after signing of Coal Operating Contract:  Fine of P20,000.00  |         |

| 1978 CMSRR                     | 2018 CMSRR  | Remarks |
|--------------------------------|---|---------|
| Chapter XII "Penal Provisions" |   |         |
| 43.                            | ii. Within one (1) month after expiration of previous permit:  Fine of P20,000.00  iii. After one (1) month after expiration of previous permit –  Fine of P40,000.00 and additional fine of P20,000.00 per month on the succeeding months  |         |
|                                | e. Failure to submit quarterly a copy of the mine maps within fifteen (15) days following the end of each quarter as set forth in Rule 49, Section 3, Chapter II of this Circular:  1st offense – P20,000.00  2nd offense – P50,000.00 with warning of cancellation  3rd offense – Cancellation of contract |         |

| 1978 CMSRR                     | 2018 CMSRR  | Remarks |
|--------------------------------|---|---------|
| Chapter XII "Penal Provisions" |   |         |
| 1.                             | f. Failure to correct unsafe conditions or non-compliance with any of the provisions of this Circular noted during inspection of Bureau's authorized representative without justifiable reasons during the next inspection: |         |
|                                | 1 <sup>st</sup> offense – <b>P20,000.00</b> 2 <sup>nd</sup> offense – <b>P50,000.00</b> with  warning of cancellation  3 <sup>rd</sup> offense – <b>Cancellation of contract</b>  |         |
|                                | g. Failure to appear when summoned during official DOE investigation without justifiable reason, five (5) working days after notification: <b>Fine of P20,000.00</b>  |         |

| 1978 CMSRR                     | 2018 CMSRR   | Remarks |
|--------------------------------|--|---------|
| Chapter XII "Penal Provisions" |  |         |
| 43.                            | h. Failure to submit quarterly Inventory of Explosive and Blasting Accessories Report within the first ten (10) days following the end of each quarter:  1st offense – P20,000.00 2nd offense – P50,000.00 with warning of cancellation 3rd offense – Cancellation of contract |         |



#### **Outline of Presentation**

- Legal Basis
- Background of the Revision Process
- ILO C176
- Scope of Coverage
- Objectives
- 1978 CMSRR vs 2018 CMSHRR
- 2018 CMSHRR Harmonized with ILO C176

# **THANK YOU**



(+632) 479-2900 / 840-2254



doecoaldivision@gmail.com



www.doe.gov.ph



//doe.gov.ph



@doe\_ph